Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO0317
Work Order Type: Weatherization
Audit Name: 14014SO0317

CLIENT INFORMATION

Client Name: Address: , Unit 562

Client ID: 14014SO0317 HAMPSHIRE, TN 38461

Alt. Client ID: LEWIS

<u>AGENCY INFORMATION</u>

Agency: South Central Human Resource Agency

Agency Phone: (931) 433-7182

Address: (PO Box 638) 1437 Winchester Highway **Fax:** (931) 433-0074

Fayetteville, TN 37334 *Email Address:*

Agency Contact: MOOREHEAD, JIMMY Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name:
Client ID: 14014SO0317
Alt. Client ID: LEWIS

Work Order (Bid Form)
Work Order Name: 14014SO0317

Report Run On: 10/6/2011

DOE Weatherization Assistant Version 8.6.0 Page 1 of 6

Measures

I	Measure 1 Infilt	ration Redctn			Componen	its			Inspected
C	THERM REPLAC	LUMBING AND ELECTE AL PANE CE DOOR UNIT 32/72 IN ONT DOOR							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	LABOR	Each						
C	ther Detail						-		
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								

	<i>Measur</i> e 2 Ligh	ting Retrofits			Componer	nts LT1,L	T1 (2),I	_T1 (3)	Inspected
C	omment								
					Estimated	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact FI 26 Watt	Each Lamp	1					
2	Labor	Compact Fl 26 Watt	Each Lamp	1					
3	Lighting	Compact FI 26 Watt	Each Lamp	1					
4	Labor	Compact FI 26 Watt	Each Lamp	1					
5	Lighting	Compact FI 26 Watt	Each Lamp	1					
6	Labor	Compact FI 26 Watt	Each Lamp	1					
(Other Detail								
				Measui	re Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 10/6/2011

Measure 3 DW	/H Pipe Insulation			Componen	ts		ı	Inspected
Comment INSUL	ATE FIRST 6 FT HOT AN	D COLD						
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	As per 2.4.1 of SWFG (page 2-11).							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
	or Ins. R-19 ATE ADDITION R 19 224	SQ FT		Componen				Inspected
# Material / Labor	Description / Comment	Units	Oti/	Estimated Unit Cost	Total	Otre	Actual Unit Cost	Total
1 Insulation	Description / Comment Floor Insulation - Fiberglass Batts - R-19	SqFt	Qty 224	Omit Cost	rotar	Qty	Omit Cost	TOTAL
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	224					
Other Detail						1		
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								

Report Run On: 10/6/2011

	Measure 5 Fix Ir	mproper Venting (Clot	hes Dryer))	Componen	ts			Inspected
C	Measure 5 Fix Improper Venting (Clothes Dryer) Comment Vent to exterior and cap as per 2.5.4 of SWFG (pages 2-17 and 2-18). Estimated Actual Material / Labor Description / Comment Health and Safety Exterior Cap / Metal Flex / Clamps Labor Hour Measure Sub Total: Measure 6 HOT WATER HEATER Components Measure 6 HOT WATER HEATER Comment INSTALL NEW 30 GAL HOT WATER HEATER Material / Labor Description / Comment Units Qty Unit Cost Total Actual Inspected Comment INSTALL NEW 30 GAL HOT WATER HEATER Units Qty Unit Cost Total Qty Unit Cost Total Actual Actual Units Qty Unit Cost Total Other Detail Measure Sub Total: Sub Total: Sub Total: Measure Sub Total: Sub Total: Sub Total: Sub Total: Measure Sub Total: Sub Total: Sub Total:								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety		Each	1					
2	Labor	Labor	Hour	3					
C	Other Detail						,		
L									
				Measur	e Sub Total:			Sub Total:	
			ATER HEA		-				Inspected
#	Material / Labor	Description / Comment	Unite	Otv			Oftv		Total
10		REPLACE HOT				rotar	Qty	Omit cost	Total
C	Other Detail								
			ı	Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 10/6/2011

	oke CARBONDetector is CARBON DRTECTOR	s Needed		Componen	ts		ı	nspecte
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Smoke carbon detector	Each	1					
2 Labor	Labor	Each	1					
Other Detail						1		
] [
			Measur	e Sub Total:]	Sub Total:	
(Bas Comment Install 6	or Barrier Needed sement/Crawlspace) mil poly as ground cover ion walls and piers 6" and				st 6". Lap			nspecte
				Estimated	<u> </u>		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	Basement / crawlspace vapor barrier	SqFt	1					
2 Labor	Labor	SqFt	1					
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								
		Work O	rder Gra	nd Total:		Gran	d Total:	

Client Name:
Client ID: 14014SO0317
Alt. Client ID: LEWIS

Work Order (Bid Form)
Work Order Name: 14014SO0317

Report Run On: 10/6/2011

DOE Weatherization Assistant Version 8.6.0 Page 6 of 6